

## RELEASE NOTES

### MiniRAE Lite+, MiniRAE 3000+, ppbRAE 3000+, UltraRAE 3000+

Version: v2.22A  
Release Date: October 2020

All users are recommended to update their existing MiniRAE Lite+, MiniRAE 3000+, ppbRAE 3000+, and UltraRAE 3000+ PID instruments with the latest firmware.

## What's New?

This new firmware implements changes for better performance of all included PID products (see “**Enhancements**” section for details).

## Installation and Update Notes

### Installation

Uploading new firmware to your instrument requires connecting the instrument and a PC. Follow these steps to make the connection:

1. Connect the data cable to the PC and the cradle.
2. Place the instrument into its cradle. The charging LED should be illuminated.
3. Start the RAEProgrammer 4000 software program on your PC.
4. From RAEProgrammer 4000, select “Operation” and select “Setup Connection.”
5. Select the COM port to establish a communication link between the PC and the instrument.
6. Select Operation → Download Firmware.

Once communication is established, follow the instructions that accompany RAEProgrammer 4000 and the firmware to upload the new firmware to your instrument.

### NOTES:

1. Use ProRAE Studio II v1.11.9 or above version for the upgrade procedure.
2. Once the instrument firmware is updated to v2.22A, the instrument cannot be downgraded back to previous FW version.
3. Instrument calibration must be done after performing the firmware upgrade (to v2.22).
4. Use ProRAE Guardian version 1.14.16

### For more information

[www.honeywellanalytics.com](http://www.honeywellanalytics.com)  
[www.raesystems.com](http://www.raesystems.com)

#### Europe, Middle East, Africa

Life Safety Distribution GmbH  
Tel: 00800 333 222 44 (Freephone number)  
Tel: +41 44 943 4380 (Alternative number)  
Fax: 00800 333 222 55  
Middle East Tel: +971 4 450 5800 (Fixed Gas Detection)  
Middle East Tel: +971 4 450 5852 (Portable Gas Detection)  
[gasdetection@honeywell.com](mailto:gasdetection@honeywell.com)

#### Americas

Honeywell Analytics Distribution Inc.  
Tel: +1 847 955 8200  
Toll free: +1 800 538 0363  
Fax: +1 847 955 8210  
[detectgas@honeywell.com](mailto:detectgas@honeywell.com)

RAE Systems by Honeywell  
Phone: 408.952.8200  
Toll Free: 1.888.723.4800  
Fax: 408.952.8480

#### Asia Pacific

Honeywell Analytics Asia Pacific  
Tel: +82 (0) 2 6909 0300  
Fax: +82 (0) 2 2025 0328  
India Tel: +91 124 4752700  
[analytics.ap@honeywell.com](mailto:analytics.ap@honeywell.com)

#### Technical Services

EMEA: [HAexpert@honeywell.com](mailto:HAexpert@honeywell.com)  
US: [ha.us.service@honeywell.com](mailto:ha.us.service@honeywell.com)  
AP: [ha.ap.service@honeywell.com](mailto:ha.ap.service@honeywell.com)

## RELEASE NOTES

### Previous Versions

MiniRAE Lite (ATEX)	FW v 2.22
MiniRAE Lite	FW v 2.22
MiniRAE3000	FW v 2.22
ppbRAE3000	FW v 2.22
UltraRAE3000	FW v 2.22

### Issue Fixes

ID	Description
PID-128	Instrument revert to Alarm default value instrument exits communication mode

### Changes

NA

### Ecosystem Compatibility:

ProRAE Studio	v 1.11.9
ProRAE Guardian	v 1.14.16
Device Communicator APP	v 2.3
AutoRAE2	v 1.38
RAElink3	v 2.22