



Honeywell Product Notification

HONEYWELL SAFETY AND PRODUCTIVITY SOLUTIONS

Date: November 18, 2022
To: Honeywell Respiratory PPE Customers
Subject: Revocation of SAF-T-FIT Approvals Labeled as Sperian Products

Please be advised that the NIOSH certification of our legacy Sperian Branded Saf-T-Fit Respirators has expired. If you happen to still have any remaining stock in inventory, we want to replace it free of charge with equivalent Honeywell disposable respiratory products.

You are receiving this notification because our records indicate you may have purchased one or more Sperian branded Saf-T-Fit products impacted by this issue in your inventory. While the Sperian products have been previously certified by NIOSH, Honeywell is issuing a replacement notice in order to help you and your customers comply with the OSHA respiratory protection standard and NIOSH revocation.



Please note, Honeywell and Sperian branded products have the exact same product code (SKU). That means that there will be no product code change or discontinuation. In order to identify which products are Sperian, you will be able to view the Sperian packaging and TC numbers on the product.

If you would like to exchange your Sperian branded Saf-T-Fit products with equivalent Honeywell disposable respiratory products, you can initiate the RMA process by sending an email to the following contacts in one message: **CustomerServiceInquiryBox@Honeywell.com**. Include the part number(s) in your possession, confirmed as Sperian brand, the quantity of units, as well as the address to which you would like the replacement item to be sent. Please respond within the next **90 days** to take advantage of this product exchange (**February 18th, 2023**). The replacement product will be sent to you once we receive the Sperian product to be replaced.



Honeywell

Below, please see packaging examples of Sperian brand vs Honeywell:

Sperian brand box (RETURN)



Honeywell brand box (KEEP)





The following Sperian TC numbers and Product SKUs are subject to the replacement notification:

SKUs	Description	Revoked TC-Number	Brand
14110387	SAF-T-FIT N1105S- 20/BOX	84A-3789	Sperian
14110388	SAF-T-FIT N1105ML -20/BOX		Sperian
14110389	SAF-T-FIT N1105XL -20/BOX		Sperian
RWS-54002	SFT+, N1105, N95, 2PK		Sperian
14110390	SAF-T-FIT N1115S -20/BOX	84A-3769	Sperian
14110391	SAF-T-FIT N1115ML-20/BOX		Sperian
14110392	RESP SAF-T-FIT N1115XL-20/BOX		Sperian
14110393	SAF-T-FIT N1125S-20/BOX	84A-3745	Sperian
14110394	SAF-T-FIT N1125M - 20/BOX		Sperian
14110395	SAF-T-FIT N1125XL-20/BOX		Sperian
14110396	SAF-T-FIT N1125OV S-10/BOX		Sperian
14110397	SAF-T-FIT N1125OV ML-10/BOX		Sperian
14110398	SAF-T-FIT N1125OV XL-10/BOX		Sperian
14110399	SAF-T-FIT N1125AG S-10/BOX		Sperian
14110400	SAF-T-FIT N1125AG ML-10/BOX		Sperian
14110401	SAF-T-FIT N1125AG XL-10/BOX		Sperian
RWS-54006	SSW,SFT+,N95,W/VALVE,N,1		Sperian
RWS-54007	WSW,SFT+,N1125 M/L,10		Sperian
14110402	SAF-T-FIT N1139 S-10/BOX		84A-3845
14110403	SAF-T-FIT N1139 ML-10/BOX	Sperian	
14110404	SAF-T-FIT N1139 XL-10/BOX	Sperian	
14110426	SAF-T-FIT P1115 ML-20/BOX	84A-3877	Sperian
14110427	SAF-T-FIT P1115 XL-20/BOX		Sperian
14110428	SAF-T-FIT P1135 ML-10/BOX		Sperian
14110429	SAF-T-FIT P1135 XL-10/BOX	84A-3879	Sperian
14110430	SAF-T-FIT P1135/1 ML-10/BOX		Sperian
14110431	SAF-T-FIT P1135/1 XL-10/BOX		Sperian
RWS-54008	SAFE-T-FIT P95 W/BNS+EV, 1 PK	84A-4270	Sperian
14110439	SAF-T-FIT P1130 SM		Sperian
14110440	SAF-T-FIT P1130 M/L		Sperian
14110441	SAF-T-FIT P1130 XL		Sperian
RWS-54020	HSP, SFT+, P100 (M/L)		Sperian
RWS-54023	SAFE-T-FIT W/BNS +EV, P100		Sperian



Honeywell values your business and regrets any inconvenience caused by this issue and will work diligently to minimize the impact on your operations.

If you need additional information or instruction, please contact:

PPE USA: 1-800-430-5490

PPE Canada: 1-888-212-7233

CustomerServiceInquiryBox@Honeywell.com

Sincerely,

Honeywell Sr Director of Marketing and Communications

Falguni Dieso