

**Quality Alert – Stop Use and Inspect Notice**

**WARNING ! Safety Risk – You must read, understand and follow all instructions carefully - YOUR IMMEDIATE ACTION IS REQUIRED**

**Date:** September 25, 2025

**Subject: Safety Notice - Miller® Falcon™+ Self-Retracting Lifeline**

Dear Customer,

We are sharing this notice regarding Miller Falcon+ Self-Retracting Lifeline (SRL) units **manufactured between March 1, 2024 and September 4, 2025**. During internal testing, we observed that certain units may not engage the activation mechanism as intended.

We have not received any customer complaints or reports of performance anomalies in the field. This communication is precautionary and intended to support safe product use. We want to assure you that the safety and strength of our products remain our top priority.

You are receiving this notice because your organization may have purchased units listed in Table 1.

**Table 1**

SKU	DESIGNATION
1017921	FALCON + SRL 10m SS TDC ATEX
1011744	Falcon + SRL MP 10m G
1011742	Falcon + SRL MP 10m G
1011950	Falcon + SRL MP 10m G
1012434	Falcon + SRL MP 10m G
1031447	Falcon + SRL MP 10m G
1011743	Falcon + SRL MP 10m SS

1011745	Falcon + SRL MP 10m SS
1028681	Falcon + SRL MP 10m SS
1012261	Falcon + SRL MP 10m SS
1011746	Falcon + SRL MP 15m G
1012436	Falcon + SRL MP 15m G
1011749	Falcon + SRL MP 15m SS
1011747	FALCON + SRL MP 15M SS
1028682	FALCON + SRL MP 15M SS
1012262	Falcon + SRL MP 15m SS
1011750	Falcon + SRL MP 20m G
1012437	Falcon + SRL MP 20m G
1013582	Falcon + SRL MP 20m G+ Carabiner Siwel .
1012263	Falcon + SRL MP 20m SS
1028683	Falcon + SRL MP 20m SS
1011751	Falcon + SRL MP 20m SS
1011753	Falcon + SRL MP 20m SS
1011728	Falcon + SRL MP 6.2m G
1012433	Falcon + SRL MP 6.2m G Steel spring TDC
1011729	Falcon + SRL MP 6.2m SS
1011741	Falcon + SRL MP 6.2m SS
1013960	Falcon + SRL MP 6.2m SS
1028680	Falcon + SRL MP 6.2M SS
1034052	FALCON EDGE Xm G (Ends)
1034053	FALCON EDGE Xm G (Ends)
1034054	FALCON EDGE Xm G (Ends)
1034055	FALCON EDGE Xm G (Ends)
1015700	TOTAL Lifeline Kit with Cardboard Box
1031447	PSS FALCON 10M GALVA CABLE TDC + EMERILL
1028812	FALCON 20m OFFSHORE KIT
1030222	Falcon Offshore 20m Kit

## REQUIRED STEPS:

### 1. Pause Use of Affected Units

Please temporarily remove the listed Miller Falcon+ Self-Retracting Lifeline units from service until inspection is completed.

### 2. Inspect Each Unit

- Locate the manufacturing date on the label atop the Miller Falcon+ Self-Retracting Lifeline housing cover.



Manufacturing Date

- Perform a Visual and Functional inspection as described in the “Retractable Inspection Sheet” (Doc ID: 90011466) : pull the cable sharply. The unit should lock immediately.
- After following the instructions, complete the attached “Recording Report” and send it to [techniserv.hsp@honeywell.com](mailto:techniserv.hsp@honeywell.com)

### 3. If the Unit Locks according to the inspection procedure:

- Your unit is working properly and is safe for use
- The unit may be returned to service.
- Use the attached recording report and send it to [techniserv.hsp@honeywell.com](mailto:techniserv.hsp@honeywell.com)

### 4. If the Unit Does Not Lock

- Set the unit aside
- Contact: [techniserv.hsp@honeywell.com](mailto:techniserv.hsp@honeywell.com)

- Our customer service team will provide instructions on how to arrange return and replacement of your unit as quick as possible

### **IMPORTANT NOTICE REGARDING UNIT VERIFICATION**

- **Units manufactured before September 4, 2025.** These have been inspected at our distribution centers and now carry a **green sticker** on the box to confirm they have passed the check and will not require additional inspection in order to assure safe use



- **Units manufactured on or after September 4, 2025.** These were produced **after corrective actions were implemented** and have also been inspected.
- **For Distributors.** Please share this notice with any customers who may have received affected units to ensure they are informed.

We appreciate your attention to this matter and your continued commitment to safety.

Marc Harkins, Director, Fall Protection